

 **AJVS.com**



*We Can Rebuild & Service your Pfeiffer MVP 015-2 PUE22001-T.*

**PFEIFFER VACUUM**

MVP 015-2 REPLACEMENT KIT

**TECHNICAL DATA**

AMBIENT TEMPERATURE: 12-40 °C

EXHAUST PRESSURE MAX: 1100 HPA

FLANGE OUT: G 1/8" PLUS SILENCER

INTAKE PRESSURE MAX: 1100 HPA

LEAK RATE: <math> < 5 \times 10^{-3}</math> HPA L/S

MOTOR RATING: 120 W



**A & J**  
VACUUM SERVICES, INC

**PFEIFFER VACUUM  
MVP 015-2 Replacement Kit**  
SALES & SERVICE 1-973-249-0854



**www.AJVS.com**

**Helium Leak  
Detector Rentals**

**Free Repair Estimate  
on all Major Brands**

**Open 24-7**

**Easily Generate  
Service RMA**

**Large Selection of New  
and Refurbished High  
Vacuum Equipment**