




PFEIFFER VACUUM
Operating Fluid Reservoir

TECHNICAL DATA

OPERATING FLUID RESERVOIR
REPLACEMENT FOR THE PFEIFFER
VACUUM HIPACE 400/700 TURBO PUMPS.
TO ENSURE THE EFFICIENCY OF YOUR
PUMP, THE LUBRICANT RESERVOIR
SHOULD BE REPLACED AT LEAST ONCE
EVERY THREE YEARS. ANY QUESTIONS,
PLEASE CONTACT OUR SALES AND
SERVICE DEPTARMENT.



We Can Rebuild & Service your HiPace Turbo Pumps



www.AJVS.com

**Helium Leak
Detector Rentals**

**Free Repair Estimate
on all Major Brands**

Open 24-7

**Easily Generate
Service RMA**

**Large Selection of New
and Refurbished High
Vacuum Equipment**